

TRANSMITTAL SLIP		
28 Mar 53 (Date)		
TO:	- for info (see below)	
BUILDING	ROOM NO.	
2. File - MDR 4		
REMARKS:		
Andy - Suggest on a low priority basis we investigate the reliability on our own of the Navy Clockwork devices. As it stands now we have no action required unless something is started by FEB to TSS.		
FROM:	WE (CLOCKWORK) ✓	
BUILDING	ROOM NO.	EXTENSION
Accomplished		

STAT

FORM NO. 35-85
NOV 1951~~CONFIDENTIAL~~

CENTRAL INTELLIGENCE AGENCY

25 MAR 53

~~SECRET~~
SECURITY INFORMATION

IN 49495

ROUTING	
1	MD
2	POD
3	FILE
4	
5	
6	
7	
8	

TO: DIRECTOR, CIA

FROM: [REDACTED] ROUTINE 25X1

ACTION: [REDACTED] 1125Z 25 MAR 53 25X1

INFORMATION: [REDACTED] PP 2, PM 5, SS 4, DD/P-ADMIN, PO 3, FI/RI 2TSGI 7134

TO: DIR INFO: [REDACTED] CITE: [REDACTED] 25X1

DIR 46225 (OUT 97783) TO [REDACTED] AS FOLLOWS PASSED [REDACTED] FOR ACTION: 25X1

1. "1. PROCURE 500 EA. DEMO FIRING DEVICE MARK 15 MOD 0 CHARGE AND DELIVER 2177-35-005 (PRESUMABLY [REDACTED] CONSUMPTION (PORTION) 25X1
GARBLED BEING SVCD).

"2. [REDACTED] INFORMS AVAIL YOUR AREA FOR 1 APRIL DEADLINE". 25X1

2. [REDACTED] SUPPLY THIS AREA ADVISES MARK 12, 13, 15 MOD 0 25X1
AVAILABLE BUT ISSUE SUSPENDED ORDER OF CHIEF [REDACTED] OPERATIONS 25X1
DUE TO DEFECTS NOTED WHICH HAVE CAUSED PREMATURE FIRING.

3. REQUEST WASHINGTON APPRAISAL AND ADVISE ALL [REDACTED] IF 25X1

DANGER EXISTS

END OF MESSAGE 25X1

*Answer is to be found in**ERDL report # 1078**22 Oct 1948
"Variable Delay Firing Devices"*~~SECRET~~
SECURITY INFORMATION

COPY NO.

~~CONFIDENTIAL~~

FORM NO. 35-85
NOV 1951

CLASSIFIED MESSAGE

CENTRAL INTELLIGENCE AGENCY

25 MAR 53

~~SECRET~~
SECURITY INFORMATION

IN 49495 A

1	MD
2	POD
3	FILE
4	
5	
6	
8	

TO: DIRECTOR, CIA

FROM: **CONFIDENTIAL** ROUTINE 25X1

ACTION: FE 6

COR TOR 0943Z 26 MAR 53

INFORMATION:

25X1

TSGI 7134

CORRECTION

CORRECT PARA 1, LINE 2 TO READ:

"CHARGE AND DELIVER 2177-35-005 (PRESUMABLY CONSUMPTION). 25X1"2. INFORMS AVAIL YOUR 25X1**CONFIDENTIAL**~~SECRET~~
SECURITY INFORMATION

COPY NO.